BEFORE THE FORUM FOR REDRESSAL OF CONSUMER GRIEVANCES IN SOUTHERN POWER DISTRIBUTION COMPANY OF A.P LIMITED TIRUPATI

On this the 18th day of July 2016

In C.G.No: 491/2015-16/Kurnool Circle

Present

Sri J.V.T.S.Prasad Sri N.Siva Shankar Prasad Sri T. Rajeswara Rao

Chairperson(I/c)
Member(Accounts)
Member (Legal)

Between

Sri D.Sakre Naik
C/o D.Sivudu Naik
D.No:1028/52 Pagidyala Road
VC Colony
Nandyal- Post Office
Nandyal
Kurnool- Dist

Complainant

AND

1.Assistant Engineer/B. Camp /Kurnool 2.Assistant Divisional Engineer/D-2/Kurnool

3.Divisional Engineer/Kurnool

Respondents

Sri D.Sakre Naik C/o D.Sivudu Naik is a resident of D.No:1028/52,VC Colony, Nandyal - Post Office, Nandyal, Kurnool -Dist, here in called the complainant, In their complaint dt:07.01.2016 filed in the Forum on dt:07.01.2016 under clause 5 (7) of APERC regulation 1/2004 read with section 42 (5) of I.E.Act 2003 has stated that:

- He is a resident of D.No:1028/52, VC Colony , Nandyal Post Office , Nandyal , Kurnool -Dist.
- 2. He is requested for Shifting of LT Line to another place.

Notices were served upon the respondents duly enclosing a copy of complaint.

C.G.No:491/2015-16/Kurnool Circle



The respondent-2 i.e. Assistant Divisional Engineer/Operation/ D-II/Kurnool in his written submission dt:15.03.2016, which is received in this office on dt:29.03.2016.03.2016 stated that:

- Sri D.Sakre Naik W/o Smt .Parvathi Bai has filed a complaint in CGRF on 07.01.2016 regarding shifting of LT line passing in the premises.
- 1 no. intermediate pole erected in between the locations of HSC No.152458 and Smt Parvathi Bai location.
- After erection of intermediate pole the LT line observed outside of the premises of the complainant. The same was intimated to the complainant over phone.
- 4. The photographs of the erection of the IP pole is here with enclosed.
- 5. This is submitted for favour of information necessary action please.

Findings of the Forum

- The complainant in his application dt:7.01.2016 stated that L.T.line was laid unauthorizedly beside his house under construction. He had requested to shift the same.
- The Assistant Divisional Engineer/D-II/Kurnool in his letter dated 15.03.2016 stated that 1 no. intermediate pole erected in between the locations of HSC No.152458 and Smt Parvathi Bai location.
- After erection of intermediate pole the LT line observed outside of the premises of the complainant. The same was intimated to the complainant over phone.
- 4. The photographs of the erection of the IP pole is here with enclosed.

ORDER

As much as the grievance of the complainant has been resolved by respondents to his satisfaction the case is disposed off.

If aggrieved by this order, the complainant may represent to the Vidyut Ombudsman, Andhra Pradesh, Flat No:401,4th Floor, Ashoka Chambers, Opposite to MLA Quarters, Adarsh Nagar, Hyderabad-500063, within 30 days from the date of receipt of this order.

Signed on this, the 18th day of July 2016

Sd/-

Sd/-

Sd/-

Member(Legal)

Member(Accounts)

Chairperson

True Copy

Chairperson

To

The Complainant

The Respondents

Copy to the General Manager/CSC/Corporate Office/ Tirupati for pursuance in this matter.